



# USRC Tiltup Seismic Retrofit Study

Achieving a USRC Gold Rating is both economical and a good investment



# Contributors

Evan Reis, US Resiliency Council  
Dustin Cook, HB-Risk  
Ali Sahabi, Optimum Seismic  
Jeff Ellis, Simpson Strongtie  
Damon Ho, Simpson Strong tie  
John Lawson, Cal Poly SLO  
David McCormick, SE, SGH  
Confidential, retailer

Project manager  
SP3 risk modeling of tilt-up designs  
Construction cost estimating  
Construction cost estimating  
Construction cost estimating  
History of tilt-up code evolution  
Structural engineering  
Building layout, replacement cost and description

# Objectives



- Consider a typical single story, big-box retail store, built to four building codes (1973 UBC, 1976 UBC, 1991 UBC, ASCE 7-10).
- 1976UBC representative of 1976-1988UBC designs. 1991UBC representative of 1991 and 1994UBC designs.
- Determine the expected USRC performance rating for each of the four designs along the dimensions of SAFETY, DAMAGE and RECOVERY.
- Estimate the cost to seismically retrofit each of the buildings to achieve a USRC GOLD rating (minimum of 4 stars in each of the three dimensions)



# Assumptions

Based on information provided by confidential retailer

|                   |  |
|-------------------|--|
| Code:             | Conforms to 1973, 1976, 1991UBC or ASCE 7-10   |
| Dimensions:       | ~135,000sf, ~500'x270' floor plan, height estimates – 24' for 1973UBC, 27' for 1976, and 1991UBC, 30' for ASCE 7-10  |
| Location:         | Los Angeles, CA (34.05, -118.25, Class D soil)   |
| Construction:     | Concrete tilt-up with panelized plywood roof and interior steel post columns. Rectangular with no significant re-entrant corners or other irregularities.        |
| Replacement cost: | ~\$142/sf = \$19.2 million   |
| Retrofit:         | Occurs simultaneously with major renovation/refresh schedule that includes replacing ceiling. Access to underside of roof is available. Roofing is not replaced. |

# Limitations



## Irregularities

Many tilt-up buildings contain irregularities such as large re-entrant corners lacking collector elements. This study does not consider buildings with these features or mezzanines

## Deterioration

Concrete, steel and wood deterioration within a building can impact seismic performance. This project assumes that the building has been well maintained.

## Rooftop equipment

Assumed properly anchored to roof.


## Age

Tilt-up buildings constructed in the 1950's, 1960's and early 1970's may have very significant deficiencies in the anchorage of walls to foundations, panel interconnections, and wall reinforcing. This study considers only buildings designed to the 1973UBC or later when many of these design deficiencies were addressed in codes.

## Soil conditions

Tilt-ups with warehouse occupancies may be located in industrial areas, near the water or other areas with poor soil conditions that can increase damage or be expensive to retrofit, in particular under wall footings and interior slabs. This study assumes a retail style building located in a suburban or urban environment without significant soil deficiencies.

# Typical Roof Diaphragm Details



## 1973 UBC


24-ft roof + 3-ft parapet, 6½" panels

Wall Anchorage:  $0.20W_p$ (ASD)

Wall Force (out-of-plane):  $0.20W_p$ (ASD)

Base Shear:  $V=0.133W$  (ASD)

Diaphragm:  $F_p=0.133W_p$ (ASD)



## 1976-1994 UBC

27-ft roof + 3-ft parapet, 7½" panels


Wall Anchorage:  $0.30W_p$ (ASD)

Wall Force (out-of-plane):  $0.30W_p$ (ASD)

50% increase in middle of diaphragm forces in 1991-1994 UBC

Base Shear:  $V=0.183W$  (ASD)

Diaphragm:  $F_p=0.183W_p$ (ASD)



## 1997 UBC and 2000+ IBC

30-ft roof + 3-ft parapet, 9¼" panels

Wall Anchorage:  $0.80W_p$ (LRFD)

Wall Force (out-of-plane):  $0.40W_p$ (LRFD)

Base Shear:  $V=0.244W$  (LRFD)

Diaphragm:  $F_p=0.25W_p$ (LRFD)

Assume 2:1 aspect ratio similar to subject building (500x270)

## Diaphragm Nailing

|        |   |
|--------|---|
| Zone 1 | 10d@ 6, 6, 12 (Boundary, panel edges, field)              |
| Zone 2 | 10d@ 4, 6, 12   |
| Zone 3 | 10d@ 2-½, 4, 12   |
| Zone 4 | 10d@ 2, 3, 12 with 3x framing at panel edges              |
| Zone 5 | 2 lines of 10d@ 2-½, 4, 12 with 4x framing at panel edges |
| Zone 6 | 2 lines of 10d@ 2-½, 3 12 with 4x framing at panel edges  |

## Diaphragm Framing

15/32" Struct I ply, panel edges align with purlins and subpurlins

2x4x8' subpurlins @ 2'oc

4x purlins 20' spans @ 8'oc

Glulam girders 40' spans @ 20'oc


Credit: John Lawson, Cal Poly SLO



# US Resiliency Council Rating System



## SAFETY



## DAMAGE



## RECOVERY



|                              |
|------------------------------|
| Blocking exit paths unlikely |
| Serious injuries unlikely    |
| Loss of life unlikely        |
| Isolated loss of life        |
| Loss of life likely          |

|                           |
|---------------------------|
| Minimal Damage (<5%)      |
| Moderate Damage (<10%)    |
| Significant Damage (<20%) |
| Substantial Damage (<40%) |
| Severe Damage (40%+)      |

|                         |
|-------------------------|
| Immediate to Days       |
| Within days to weeks    |
| Within weeks to months  |
| Within months to a year |
| More than a year        |



Resilience Based Design

PLATINUM

GOLD

SILVER

Code Based Design

CERTIFIED



# Approximate USRC Safety Performance

- Based on SEAONC EPRS and ASCE 41-13 (NC = Nonconforming, C=Conforming)
- Based on discussions with Dr. John Lawson and David McCormick, SE

| PC1 (Precast/Tilt-Up Concrete Shearwalls - Flexible Diaphragms) |  | EPRS Rating | 1973 UBC    | 1976 UBC | 1991 UBC     | ASCE 7-10                              |
|---|--|-------------|-------------|----------|--------------|--|
| 16.12LS   | WALL ANCHORAGE                               | 2 Stars     | NC          | NC       | NC           | Conforming by ASCE 41 benchmark status |
| 16.12LS   | REDUNDANCY                                   | 3 Stars     | C           | C        | C            |  |
| 16.12LS   | WALL SHEAR STRESS CHECK                      | 2 Stars     | C           | C        | C            |  |
| 16.12LS   | REINFORCING STEEL                            | 3 Stars     | Close       | C        | C            |  |
| 16.12LS   | WALL THICKNESS                               | 3 Stars     | NC          | C        | C            |  |
| 16.12LS   | WOOD LEDGERS                                 | 2 Stars     | Possibly NC | C        | C            |  |
| 16.12LS   | TRANSFER TO SHEAR WALLS                      | 2 Stars     | NC          | NC       | NC           |  |
| 16.12LS   | GIRDER-COLUMN CONNECTION                     | 2 Stars     | NC          | NC       | NC           |  |
| 16.12LS   | WALL OPENINGS                                | 2 Stars     | C           | C        | C            |  |
| 16.12LS   | CROSS TIES IN FLEXIBLE DIAPHRAGMS            | 2 Stars     | NC          | NC       | NC           |  |
| 16.12LS   | STRAIGHT SHEATHING                           | 2 Stars     | C           | C        | C            |  |
| 16.12LS   | SPANS  | 2 Stars     | C           | C        | C            |  |
| 16.12LS   | DIAGONALLY SHEATHED AND UNBLOCKED DIAPHRAGMS | 2 Stars     | C           | C        | C            |  |
| 16.12LS   | OTHER DIAPHRAGMS                             | 2 Stars     | C           | C        | C            |  |
| 16.12LS   | MINIMUM NUMBER OF WALL ANCHORS PER PANEL     | 2 Stars     | C           | C        | C            |  |
| 16.12LS   | PRECAST WALL PANELS                          | 2 Stars     | C           | C        | C            |  |
| 16.12LS   | UPLIFT AT PILE CAPS                          | 3 Stars     | ?           | C        | C            |  |
| Approximate USRC SAFETY Rating                                  |  |             | 1 star      | 1 star   | 1 to 2 stars | 4 to 5 stars*                          |

\* Assumes seismic bracing of ceilings and light fixtures + racks > 6' tall, required as part of standard remodel

Credit: SEAONC, ASCE



# Expected Seismic Performance

- Based on information provided by HB-Risk, ASCE 41-13 and SEAONC EPRS
- 500' x 270' floor plate
- Based on Design Level event with return period in Los Angeles ~711 years

| CODE LEVEL | USRC RATING  |              |                                |
|------------|--------------|--------------|--------------------------------|
|            | SAFETY*      | DAMAGE       | RECOVERY**                     |
| 1973 UBC   | 1 star       | 28% (2 star) | 99 days (3 star) <sup>†</sup>  |
| 1976 UBC   | 1 star       | 26% (2 star) | 95 days (3 star) <sup>†</sup>  |
| 1991 UBC   | 1 to 2 stars | 21% (2 star) | 86 days (3 star) <sup>†</sup>  |
| ASCE 7-10  | 4 to 5 stars | 8% (4 star)  | 15 days (4 star) <sup>††</sup> |

\* Based on ASCE 41-13 and SEAONC EPRS

\*\* Assumes retailer has a BORP program and financing in place

<sup>†</sup> Assumes at least some structural damage that may produce a Yellow Tag, where city closes building until structural repairs are completed following issuance of a permit (8wk permitting delay as per REDi)

<sup>††</sup> Minimal structural damage and Green Tag expected, allowing for occupancy while repairs are ongoing, so no permitting delay. Recovery time based on time required to restore basic functionality



# Retrofit



- Based on results from HB-Risk study, 1997UBC and later designed buildings, can achieve a USRC GOLD rating so long as rapid response measures are put in place: post event inspection, retainers with contractors, and adequate financing. For national big-box retailers all three are well within their capabilities. This eliminates REDi impeding factors that can substantially extend repair times.
- Therefore, the retrofit expectation will be that pre 1997UBC buildings will be brought into conformance with the 1997UBC/2000IBC.
- The HB-Risk study indicates that little damage occurs in the tilt-up walls themselves, either in- or out-of-plane, at the design level event, so that retrofit will be limited to the roof diaphragm and its connections to the walls.
- Assumption is also that in a major renovation/refresh for retailer, the existing ceiling is dropped and replaced with a current code compliant ceiling, including grid and light fixture bracing.

# Retrofit Assumptions



- Per the study by John Lawson, requirements for concentric wall and crosstie anchors appeared in the 1997UBC.
- 1973UBC – Assume old style wall-roof, subdiaphragm and crosstie connections will be completely replaced because of eccentric connections and low design forces.
- 1976-1994UBC – Assume wall-roof and crosstie connections will be doubled up in order to become concentric. The increase in wall anchorage forces from  $0.30W_p$  (ASD) to  $0.80W_p$  (LFRD) would be achieved by the additional anchors.
- 1976-1994UBC – Assume subdiaphragm details are all replaced in direction parallel to 4x purlins, and use newer style detail with block between subpurlins.
- All nailing augmentation done from below roof.
- Plywood is oriented with panel edges aligned with 2x4 subpurlins and 4x purlins so that supplementary blocking is not needed.
- (E) 2x4 subpurlins need to be doubled where panel edge nailing requires 3x or 4x elements.

# Retrofit Details

1973UBC brought to compliance with  
1997UBC



## Wall anchors

Parallel to girders: Use (e) 4x14 purlins (DETAIL D) @ 8'oc

Double Simpson HDU4-SDS2.5 with 5/8" rod

Perp to girders: Space at 8' oc use block between purlins 16' back (DETAIL B) 4x block with Simpson 2-HUC hanger, 5/8"x16' rod and 3" pl

## Crossties

On girders at 20'OC: Ties at 40' girder span (DETAIL F)

Double Simpson HCSTR4 with 3/4" bolts

On purlins at 40'OC: Ties at 20' purlin span (DETAIL G)

Double Simpson HHDQ11 with 1" rod

## Girder to wall ties

At 20'OC parallel to long direction (DETAIL E)

Double Simpson HHDQ11 with 1" rod

## Sub diaphragms

Parallel to girders: use (e) 4x14 purlins with std wall anchors (DETAIL D)

Wall anchors achieve this

Perp to girders: space at 8' oc use block between purlins 16' back (DETAIL B)

Wall anchors achieve this

## Diaphragm nailing augmentation

Calculate average boundary nailing for 1973 and 1997 UBC designs and augment nailing with clips to achieve equivalent average spacing (DETAIL H).

- Simpson A35 clips with #6x1/2" screws to underside of plywood deck or as a preferred alternative, renail from above when roofing is replaced. The nailing will be lower cost when done from above.
- Assume (e) ledgers at wall edges are 3x or 4x Where 1997 UBC panel edge requirements require 3x or 4x at subpurlins, double up (e) 2x4.

Note: Based on cost estimates provided by Simpson Strongtie variation as a function of the precise size of the hold down anchors is relatively small compared with the average material and installation cost. Therefore, the selection of specific anchor was based on simplified calculations.

# Retrofit Details

1976 and 1991UBC brought to compliance with 1997UBC



## Wall anchors

Parallel to girders: Use (e) 4x14 purlins (DETAIL D), assuming 1-sided connection already exists Single Simpson HDU4-SDS2.5 with 5/8" rod  
Perp to girders: Space at 8' oc use block between purlins 16' back (DETAIL B) 4x block with Simpson 2-HUC hanger, 5/8"x16' rod and 3" plate

## Diaphragm crossties

On girders at 20'OC: Ties at 40' girder span (DETAIL F), assuming 1-sided connection already exists Single Simpson HCSTR4 with 3/4" bolts

On purlins at 40'OC: Ties at 20' purlin span (DETAIL G) , assuming 1-sided connection already exists Single Simpson HHDQ11 with 1" rod

## Girder to wall ties

At 20'OC parallel to long direction (DETAIL E), assuming 1-sided connection already exists Single Simpson HHDQ11 with 1" rod

## Sub diaphragms

Parallel to girders: use (e) 4x14 purlins with std wall anchors (DETAIL D)

Perp to girders: space at 8' oc use block between purlins 16' back (DETAIL B)

Wall anchors achieve this  
wall anchors achieve this

## Diaphragm nailing augmentation

Calculate average boundary nailing for 1976 and 1997 UBC designs and augment nailing with clips to achieve equivalent average spacing (DETAIL H). Augmentation would be slightly less for 1991 UBC where higher forces in middle half of diaphragm were assumed.

- Simpson A35 clips with #6x1/2" screws to underside of plywood deck or as a preferred alternative, renail from above when roofing is replaced. The nailing will be lower cost when done from above.
- Assume (e) ledgers at wall edges are 3 or 4x Where panel edge requirements require 3 or 4x at subpurlins, double up (e) 2x4 .



# Retrofit Quantities

1973UBC brought to compliance  
with 1997UBC



| Connection   | Piece*                     | Rod                  | Other                             | Detail |
|--|----------------------------|----------------------|-----------------------------------|--------|
| Purlin to tiltup wall anchors<br>(epoxied into 6" wall)    | (246) HDU4-SDS2.5          | (246) 5/8" rod x 18" |                                   | D      |
| Subpurlin to tiltup wall anchors<br>(epoxied into 6" wall) | (132) HUC hangers          | (66) 5/8"dia x 16'   | (66) 3" bearing pl.               | B      |
| Girder crossties   | (288) HCSTR4 w/ 3/4" bolts |                      |                                   | F      |
| Purlin crossties   | (576) HHDQ11               | (288) 1" rods x 24"  |                                   | G      |
| Girder to wall connection                                  | (50) HHDQ11                | (50) 1" rods x 18"   |                                   | E      |
| Diaphragm strengthening                                    | (25,000) A35               |                      | PH6-121 screws to<br>plywood deck | H      |
| Subpurlin augmentation                                     | (1,000) 2x4x8'             |                      |                                   |        |

\* (x) Refers to the total number of pieces, not the total number of detail locations



# Retrofit Quantities

1973 and 1991UBC brought to compliance with 1997UBC



| Connection  | Piece*            | Rod                  | Other                          | Detail |
|---|-------------------|----------------------|--------------------------------|--------|
| Purlin to tiltup wall anchors (epoxied into 6" wall)    | (123) HDU4-SDS2.5 | (123) 5/8" rod x 18" |                                | D      |
| Subpurlin to tiltup wall anchors (epoxied into 6" wall) | (132) HUC hangers | (66) 5/8"dia x 16'   | (66) 3" bearing pl.            | B      |
| Girder crossties  | (144) HCSTR4      |                      |                                | F      |
| Purlin crossties  | (288) HHDQ11      | (144) 1" rods x 24"  |                                | G      |
| Girder to wall connection                               | (25) HHDQ11       | (25) 1" rods x 18"   |                                | E      |
| Diaphragm strengthening                                 | (6,000) A35       |                      | PH6-121 screws to plywood deck | H      |
| Subpurlin augmentation                                  | (325) 2x4x8'      |                      |                                |        |

\* (x) Refers to the total number of pieces, not the total number of detail locations

\*\* 1991 and 1994UBC increased OOP forces at middle half of diaphragm so this retrofit would be a bit conservative

# Retrofit Details

From FEMA 547








Figure 16.4.2-3: Enhanced Girder Connection at Pilaster

Credit: FEMA

# Retrofit Details

From FEMA 547 and  
Simpson Strongtie







Figure 22.2.3-1A: Roof Plan with Diaphragm Cross-Tie System Using Subdiaphragms, Shown for Wood Diaphragm

Credit: FEMA




Credit: Simpson





# Retrofit Pricing



- Price includes materials, installation and inspections
- General conditions, profit and overhead included.
- Mobilization and demolition of ceilings not included because during renovation and refresh process, contractor will already incur these costs.
- Costs are averaged from estimates provided by Simpson Strongtie, Optimum Seismic and Concrete West.

| Connection   | Material         | Unit list price | Cost 1973UBC |           | Cost 1976 through 1994 UBC |           |
|--|------------------|-----------------|--------------|-----------|----------------------------|-----------|
| Sub-purlin wall anchors  | HUC hangers      | \$29.86         | 132          | \$15,028  | \$132                      | \$14,805  |
| Purlin wall anchors  | HDU4-SDS2.5      | \$32.10         | 246          | \$27,316  | \$123                      | \$14,686  |
| Girder crossties   | HCSTR4 w/¾"bolts | \$57.87         | 288          | \$52,487  | \$144                      | \$28,787  |
| Purlin crossties   | HHDQ11           | \$109.55        | 576          | \$174,398 | \$288                      | \$88,929  |
| Girder to wall connection  | HHDQ11           | \$113.30        | 50           | \$16,634  | \$25                       | \$8,723   |
| Diaphragm strengthening  | A35              | \$1.25          | 25,000       | \$131,344 | \$6,000                    | \$31,085  |
| Sub-purlin augmentation  | 2x4x8'           | \$2.50          | 1,000        | \$30,678  | \$325                      | \$9,738   |
| Total  |                  |                 |              | \$447,887 |                            | \$196,752 |
| \$/sf  |                  |                 |              | \$3.32    |                            | \$1.46    |
| % of Replacement Cost  |                  |                 |              | 2.3%      |                            | 1.0%      |
| * All markups distributed to line items: Installation, Permits, Rentals, Inspections, GC, OH, Profit |                  |                 |              |           |                            |           |



# Pricing Provided by Confidential Retailer

- Pricing provided from retailer for two recent Southern California project and which includes all markups.
- Location impacts costs significantly. Urban and coastal areas are typically more expensive.
- The specific retrofit implemented was provided for Location 2. It is similar to that proposed in this study.

## Location 1

- Range of cost is \$4 to \$5 per square foot
- \$540,000 to \$675,000
- 2.8% to 3.5% of replacement cost

## Location 2

- \$2 per square foot
- \$222,000
- 1.4% of replacement cost




# Retrofit Details

## From Confidential Retailer




### Cost Data


Hardware: \$54,701  
Lumber: \$25,350  
Labor: \$142,072




- (28) LOCATIONS @ 17FT EA  
REQUIRES:  
(1) 3.5" x 11.875" LVL  
(2) 1/2" x 5-1/2" LAG SCREWS @ 12" OC




- (90) LOCATIONS  
REQUIRES:  
(2) 1/4" CORE THRU (E) I-BEAM WEB  
(2) HD RODS  
(4) SIMPSON HD9B




- (136) LOCATIONS  
REQUIRES:  
(1) SIMPSON CS14 x 2'-10" LONG STRAP



- (99) LOCATIONS  
REQUIRES:  
(2) 2x W/ (4) 5/8" THRU BOLTS  
(2) ALL THREAD RODS SET IN EPOXY  
(2) SIMPSON HD5B



- (166) LOCATIONS  
REQUIRES:  
(1) 4x SISTER (APPROX. 6ft LENGTH) W/ 16x  
(2) ALL THREAD RODS SET IN EPOXY  
(2) SIMPSON HD5B







# Summary

To achieve a **USRC GOLD** rating, assuming post earthquake engineering inspection and contractor mobilization retainers are in place, and retailer has adequate financing in place so that REDi impeding factors are not triggered.

*Building parameters: 135,000sf, 500'x270' floorplan, no irregularities, \$19,200,000 replacement cost, located in Los Angeles*

|  |  |
|--|--|
| Cost to retrofit a 1973UBC compliant building:   | \$448,000<br>\$3.32 / sq.ft.<br>2.3% of replacement cost |
| Cost to retrofit a 1976UBC through 1994UBC compliant building:   | \$197,000<br>\$1.46 / sq.ft.<br>1.0% of replacement cost |
| Cost to achieve USRC GOLD for a 1997UBC or later building:<br>(With inspection, mobilization and financing in place) | \$0  |





# Return on Improved Performance

- Older buildings retrofitted to be USRC Gold compliant
- Building replacement cost value (RCV): \$19,200,000
- Average CA store revenue based on public information ~ \$134,000 per day

| DAMAGE IN A DESIGN LEVEL EVENT * |          |             |                |                 |             |                 |              |               |     |
|----------------------------------|----------|-------------|----------------|-----------------|-------------|-----------------|--------------|---------------|-----|
|                                  | Damage   |             |                | Recovery (days) |             |                 | Total Return | Retrofit Cost | BCR |
| CODE LEVEL                       | Existing | Retrofitted | Savings at RCV | Existing        | Retrofitted | Revenue savings |              |               |     |
| 1973 UBC                         | 28.3%    | 7.6%        | \$3,970,000    | 99              | 15          | \$11,210,000    | \$15,180,000 | \$448,000     | 34  |
| 1976 UBC                         | 25.9%    | 7.6%        | \$3,510,000    | 95              | 15          | \$10,680,000    | \$14,190,000 | \$197,000     | 72  |
| 1991 UBC                         | 21.3%    | 7.6%        | \$2,630,000    | 86              | 15          | \$9,480,000     | \$12,110,000 | \$197,000     | 61  |

\* From SP3 evaluation Design Event has 711 year return period at Los Angeles site.



# Return on Improved Performance to Achieve USRC Gold Rating

- Annualize ROI when older buildings retrofitted to be USRC Gold compliant
- Building replacement cost value (RCV): \$19,200,000
- Average CA store revenue based on public information ~ \$134,000 per day

| ANNUAL DAMAGE AND RETURNS * |                      |             |                |                                |             |                 |                               |               |            |                           |                   |
|-----------------------------|----------------------|-------------|----------------|--------------------------------|-------------|-----------------|-------------------------------|---------------|------------|---------------------------|-------------------|
|                             | Average Annual Loss* |             |                | Average Annual Recovery (days) |             |                 | Total Annual Savings (Return) | Retrofit Cost | Annual ROI | PV Return over 10 years** | BCR over 10 years |
| CODE LEVEL                  | Existing             | Retrofitted | Savings at RCV | Existing                       | Retrofitted | Revenue savings |                               |               |            |                           |                   |
| 1973 UBC                    | 0.42%                | 0.06%       | \$69,696       | 2.37                           | 0.27        | \$281,264       | \$350,960                     | \$447,887     | 78%        | \$2,846,597               | 6.4               |
| 1976 UBC                    | 0.38%                | 0.06%       | \$62,016       | 1.98                           | 0.27        | \$228,268       | \$290,284                     | \$196,752     | 148%       | \$2,354,461               | 12.0              |
| 1991 UBC                    | 0.28%                | 0.06%       | \$42,048       | 1.50                           | 0.27        | \$164,974       | \$207,022                     | \$196,752     | 105%       | \$1,679,136               | 8.5               |

\* From SP3 evaluation, average annual values include overall earthquake risk from multiple events on an annualized basis.

\*\* 10 years is recommended by retailer

# Design Performance Goal for New Buildings



- Buildings built to current code are likely to receive a USRC Gold Rating with no additional construction costs
- Owner needs to have in place:
  - Business Recovery program that includes engineering inspection and contractor mobilization
  - Adequate financing to complete repairs

|            | USRC RATING  |             |                  |
|------------|--------------|-------------|------------------|
| CODE LEVEL | SAFETY       | DAMAGE      | RECOVERY         |
| ASCE 7-10  | 4 to 5 stars | 8% (4 star) | 15 days (4 star) |

